



**Federal Public Service  
Mobility and Transport**  
Belgian Civil Aviation Authority

**Company Approvals Directorate**  
**Operations Department**

## NOTICE TO OPERATORS 11/07

**Subject:** EASA Safety Information Bulletin 2011-14 on mode S transponder


**Date:** 18 July 2011

**Description:** EASA has issued a Safety Information Bulletin (SIB No 2011-14) related to "Mode S Transponder – Incorrect Setting of ICAO 24-bit Aircraft Address". This SIB is available on the website:

<http://ad.easa.europa.eu/sib-docs/page-1>

This SIB recommends that the operators take action to ensure that the address of your aircrafts are set correctly (as assigned to your aircrafts).

Moreover, the Belgian CAA ask to the Belgian operators to pay attention to the input of manual information into the transponder (flight number) according to the approved Operations Manual.

  
Jean-Paul LEROY

B. Van Noten, Ir.  
Counsellor General

